



Intel[®] Xeon[™] Processor Specification Update

Release Date: July 2001

Order Number: 249678-004

The Intel[®] Xeon[™] processor may contain design defects or errors known as errata that may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® Xeon™ processor may contain design defects or errors known as errata that may cause the product to deviate from published specifications. Current characterized errata are available on request.

The Specification Update should be publicly available following the last shipment date for a period of time equal to the specific product's warranty period. Hardcopy Specification Updates will be available for one (1) year following End of Life (EOL). Web access will be available for three (3) years following EOL.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com>

Copyright © Intel Corporation 2001.

Intel, Intel logo, Pentium, and MMX are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

* Other names and brands may be claimed as the property of others.

CONTENTS

REVISION HISTORY	ii
PREFACE	iii
Specification Update for the Intel® Xeon™ Processor	
GENERAL INFORMATION	1
INTEL® XEON™ PROCESSOR MARKINGS (31 mm OLGA)	1
IDENTIFICATION INFORMATION	2
SUMMARY OF CHANGES	4
Summary of Errata	5
Summary of Documentation Changes	6
Summary of Specification Clarifications	6
Summary of Specification Changes	6
ERRATA	7
DOCUMENTATION CHANGES	20
SPECIFICATION CLARIFICATIONS	21
SPECIFICATION CHANGES	22

REVISION HISTORY

Date of Revision	Version	Description
May 2001	-001	Initial Release
June 2001	-002	Added errata P27-P28.
June 2001	-003	Updated erratum P25.
July 2001	-004	Added RCPPS, RCPSS, RSQRTPS and RSQRTSS Instruction Specification Clarification

PREFACE

This document is an update to the specifications contained in the following documents:

- *Intel® Xeon™ Processor at 1.40 GHz, 1.50 GHz, and 1.70 GHz* datasheet (Order Number 249665)
- *IA-32 Intel® Architecture Software Developer's Manual, Volumes 1, 2 and 3* (Order Numbers 245470, 245471, and 245472, respectively)

It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It contains S-Specs, Errata, Documentation Changes, Specification Clarifications and Specification Changes.

Nomenclature

S-Spec Number is a five-digit code used to identify products. Products are differentiated by their unique characteristics, e.g., core speed, L2 cache size, package type, etc., as described in the processor identification information table. Care should be taken to read all notes associated with each S-Spec number.

Errata are design defects or errors. Errata may cause the Intel® Xeon™ processor's behavior to deviate from published specifications. Hardware and software designed to be used with any given processor must assume that all errata documented for that processor are present on all devices unless otherwise noted.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Specification Changes are modifications to the current published specifications for the Intel Xeon processor. These changes will be incorporated in the next release of the specifications.

Specification Update for the Intel® Xeon™ Processor

GENERAL INFORMATION

INTEL® XEON™ PROCESSOR MARKINGS (31 mm OLGA)

Figure 1. Top Side Processor Marking





Figure 2. Bottom Side Processor Marking





IDENTIFICATION INFORMATION

The Intel® Xeon™ processor can be identified by the following values:

Family ¹	Model ²	Brand ID ³
1111	0000	00001110

NOTES:

1. The Family corresponds to bits [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
2. The Model corresponds to bits [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.
3. The Brand ID corresponds to bits [7:0] of the EBX register after the CPUID instruction is executed with a 1 in the EAX register.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register. Please refer to the *Intel Processor Identification and the CPUID Instruction Application Note (AP-485)* for further information on the CPUID instruction.



Intel® Xeon™ Processor Identification and Package Information

S-Spec Number	Core Stepping	CPUID	Speed Core/System Bus (MHz)	L2 Size (Kbytes)	Processor Interposer Revision	Package and Revision	Notes
SL4WX	C1	0F0Ah	1.40/400	256K	B0	31 mm OLGA rev 2.0	1
SL56G	C1	0F0Ah	1.40/400	256K	B0	31 mm OLGA rev 2.0	1, 2
SL4WY	C1	0F0Ah	1.50/400	256K	B0	31 mm OLGA rev 2.0	1
SL4ZT	C1	0F0Ah	1.50/400	256K	B0	31 mm OLGA rev 2.0	1, 2
SL56N	C1	0F0Ah	1.70/400	256K	B0	31 mm OLGA rev 2.0	1
SL56H	C1	0F0Ah	1.70/400	256K	B0	31 mm OLGA rev 2.0	1, 2

NOTES:

1. These parts require the inputs from A20M#, IGNNE#, LINT[1]/NMI and LINT[0]/INTR pins during RESET to set the correct core to bus frequency ratio.
2. These parts are Intel boxed processors.

SUMMARY OF CHANGES

The following table indicates the Errata, Documentation Changes, Specification Clarifications, or Specification Changes that apply to Intel Xeon processors. Intel intends to fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

CODES USED IN SUMMARY TABLE

X:	Erratum, Documentation Change, Specification Clarification, or Specification Change applies to the given processor stepping.
(No mark) or (blank box):	This item is fixed in or does not apply to the given stepping.
Fix:	Intel intends to fix this erratum in a future stepping of the component.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Doc:	Intel intends to update the appropriate documentation in a future revision.
PKG:	This column refers to errata on the Intel Xeon processor substrate.
AP:	APIC related erratum.
Shaded:	This item is either new or modified from the previous version of the document.

Each Specification Update item is prefixed with a capital letter to distinguish the product. The key below details the letters that are used in Intel's microprocessor Specification Updates:

A = Intel® Pentium® II processor

B = Intel® Mobile Pentium® II processor

C = Intel® Celeron™ processor

D = Intel® Pentium® II Xeon™ processor

E = Intel® Pentium® III processor

G = Intel® Pentium® III Xeon™ processor

H = Intel® Mobile Celeron™ processor at 466 MHz 433 MHz, 400 MHz, 366 MHz, 333 MHz, 300 MHz, and 266 MHz

K = Intel® Mobile Pentium® III processor

M = Intel® Mobile Celeron™ processor at 500 MHz, 450 MHz, and 400A MHz

N = Intel® Pentium® 4 processor

P = Intel® Xeon™ processor

The Specification Updates for the Pentium® processor, Pentium® Pro processor, and other Intel products do not use this convention.

Summary of Errata

NO.	C1	PKG	Plans	ERRATA
P1	X		NoFix	UC Code in same line as WriteBack (WB) data may lead to data corruption
P2	X		NoFix	Transaction is not retried after BINIT#
P3	X		NoFix	Invalid opcode 0FFFH requires a ModRM byte
P4	X		NoFix	When in No-Fill Mode (CR0.CD=1) the memory type of large (PSE-4M and PAE-2M) pages are wrongly forced to uncacheable
P5	X		NoFix	Processor may hang due to Speculative Page Walks to Non-Existent System Memory
P6	X		NoFix	Writing a performance counter may result in an incorrect counter value
P7	X		NoFix	Performance Counter May Contain Incorrect Value After Being Stopped
P8	X		Fix	REP MOV instruction with overlapping source and destination may result in data corruption
P9	X		NoFix	Memory type of the load lock different from its corresponding store unlock
P10	X		NoFix	Machine check architecture error reporting and recovery may not work as expected
P11	X		NoFix	Debug mechanisms may not function as expected
P12	X		Fix	Processor may live-lock if PDEs or PTEs are in UC space
P13	X		Fix	Thermal status log bit may not be set when the Thermal Control Circuit is Active
P14	X		NoFix	Processor may timeout waiting for a device to respond after 0.67 seconds
P15	X		NoFix	Cascading of performance counters does not work correctly when forced overflow is enabled
P16	X		NoFix	EMON event counting of X87 loads may not work as expected
P17	X		NoFix	Simultaneous code breakpoint and uncorrectable error results in a processor hang
P18	X		NoFix	Software controlled clock modulation using a 12.5% or 25% duty cycle may cause the processor to hang
P19	X		Fix	RFO with ECC error may result in incorrect data
P20	X		Fix	Speculative page fault may cause livelock
P21	X		Fix	PAT index MSB may be calculated incorrectly
P22	X		NoFix	System bus interrupt messages without data and which receive a HardFailure response may hang the processor

Summary of Errata

NO.	C1	PKG	Plans	ERRATA
P23	X		NoFix	SQRTPD and SQRTSD May Return QNaN Indefinite Instead of Negative Zero
P24	X		Fix	Bus Invalidate Line Request that returns unexpected data may result in L1 cache corruption
P25	X		Fix	Multi-processor boot protocol may not complete with an IOQ depth of one
P26	X		NoFix	Processor flags #PF instead of #AC on an unlocked CMPXC8B instruction
P27	X		NoFix	Incorrect data may be returned when page tables are located in Write Combining (WC) memory
P28	X		NoFix	FSW may not be completely restored after page fault on FRSTOR or FLDENV instructions

Summary of Documentation Changes

NO.	C1	PKG	Plans	Documentation Changes
				There are no documentation changes

Summary of Specification Clarifications

NO.	C1	PKG	Plans	Specification Clarifications
P1	X		Fix	RCPPTS, RSPSS, RSQRTPS and RSQRTSS Instruction Documentation Clarification

Summary of Specification Changes

NO.	C1	PKG	Plans	Specification Changes
				There are no specification changes

ERRATA

P1. UC Code in Same Line as WriteBack (WB) Data may Lead to Data Corruption

Problem: This erratum occurs when both code (being accessed as UC or WC) and data (being accessed as WB) are placed in the same cache line. The UC fetch will cause the processor to self-snoop and generate an implicit writeback. The data supplied by this implicit writeback may be corrupted due to the way the processor is currently handling self-modifying code.

Implication: UC code located in the same cache line as WB data may lead to data corruption.

Workaround: UC or WC code should not be located in the same 64 byte cache line as any location that is being stored to with WB data.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P2. Transaction Is Not Retried After BINIT#

Problem: If the first transaction of a locked sequence receives a HITM# and DEFER# during the snoop phase it should be retried and the locked sequence restarted. However, if BINIT# is also asserted during this transaction, the transaction will not be retried.

Implication: When this erratum occurs, locked transactions will not be retried.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P3. Invalid Opcode 0FFFh Requires A ModRM Byte

Problem: Some invalid opcodes require a ModRM byte and other following bytes, while others do not. The invalid opcode 0FFFh did not require a ModRM in previous generation microprocessors such as Pentium® II or Pentium III processors, but it is required in the Intel® Xeon™ processor

Implication: The use of an invalid opcode 0FFFh without the ModRM byte may result in a page or limit fault on the Intel Xeon processor.

Workaround: To avoid this erratum use ModRM byte with invalid 0FFFh opcode.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P4. When in No-Fill Mode (CR0.CD=1) the Memory Type of Large (PSE-4M and PAE-2M) Pages are Wrongly Forced to Uncacheable

Problem: When the processor is operating in No-Fill Mode (CR0.CD=1), the page miss hardware incorrectly forces the memory type of large (PSE-4M and PAE-2M) pages to UC memory type regardless of the MTRR settings. By forcing the memory type of these pages to UC, load operations, which should hit valid data in the L1 cache, are forced to load the data from system memory. Some applications will lose the performance advantage associated with the caching permitted by other memory types.

Implication: This erratum may result in some performance degradation when using no-fill mode with large pages.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P5. Processor May Hang Due to Speculative Page Walks to Non-Existent System Memory

Problem: A load operation issued speculatively by the processor that misses the Data Translation Lookaside Buffer (DTLB) results in a page walk. A branch instruction older than the load retires so that this load operation is now in the mispredicted branch path. Due to an internal boundary condition, in some instances the load is not canceled before the page walk is issued.

The Page Miss Handler (PMH) starts a speculative page-walk for the Load and issues a cacheable load of the Page Directory Entry (PDE). This PDE load returns data that points to a page table entry in uncacheable (UC) memory. The PMH issues the PTE Load to UC space, which is issued on the system bus. No response comes back for this load PTE operation since the address is pointing to system memory, which does not exist.

This load to non-existent system memory causes the processor to hang because other bus requests are queued up behind this UC PTE load, which never gets a response. If the load was accessing valid system memory, the speculative page-walk would successfully complete and the processor would continue to make forward progress.

Implication: Processor may hang due to speculative page walks to non-existent system memory

Workaround: Page directories and page tables in UC memory space must point to system memory that exists.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P6. Writing a Performance Counter May Result in an Incorrect Counter Value

Problem: Accessing a performance counter also enables the counter input so that writing one half of the counter can cause the other half to increment. When a performance counter is written and the event counter for the event being monitored is non-zero, the performance counter will be incremented by the value on that event counter. Because the upper eight bits of the performance counter are not written at the same time as the lower 32 bits, the increment due to the non-zero event counter may cause a carry to the upper bits such that the performance counter contains a value higher than what was written. The worst case error caused by this can be about 4 billion counts.

Implication: When this erratum occurs, the performance counter will contain a different value from that which was written.

Workaround: If the performance counter is set to select a null event and the CCCR for that counter has its compare bit set to zero, before the performance counter is written, this erratum will not occur.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P7. Performance Counter May Contain Incorrect Value After Being Stopped

Problem: If a performance counter is stopped on the precise internal clock cycle where the intermediate carry from the lower 32 bits of the counter to the upper eight bits occurs, the intermediate carry is lost.

Implication: When this erratum occurs the performance counter may contain a value about 4 billion (2^{32}) less than it should.

Workaround: Since this erratum does not occur if the performance counters are read when running, a possible workaround is to read the counter before stopping it.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P8. REP MOV Instruction with Overlapping Source and Destination may Result in Data Corruption

Problem: When fast strings are enabled and a REP MOV instruction is used to move a string and the source and destination strings overlap by 56 bytes or less, data corruption may occur.

Implication: When this erratum occurs, data corruption may occur.

Workaround: It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P9. Memory Type of the Load Lock Different from its Corresponding Store Unlock

Problem: The Intel® Xeon™ processor employs a use-once protocol to ensure that a processor in a multi-processor system may access data that is loaded into its cache on a Read-for-Ownership operation at least once before it is snooped out by another processor. This protocol is necessary to avoid a dual processor livelock scenario where no processor in the system can gain ownership of a line and modify it before that data is snooped out by another processor. In the case of this erratum, the use-once protocol incorrectly activates for split load lock instructions. A load lock operation accesses data that splits across a page boundary with both pages of WB memory type. The use-once protocol activates and the memory type for the split halves get forced to UC. Since use-once does not apply to stores, the store unlock instructions go out as WB memory type. The full sequence on the Bus is: locked partial read (UC), partial read (UC), partial write (WB), locked partial write (WB). The Use-once protocol should not be applied to Load locks.

Implication: When this erratum occurs, the memory type of the load lock will be different than the memory type of the store unlock operation. This behavior (Load Locks and Store Unlocks having different memory types) does not however introduce any functional failures such as system hangs or memory corruption.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P10. Machine Check Architecture Error Reporting and Recovery May Not Work as Expected

Problem: When the processor detects errors it should attempt to report and/or recover from the error. In the situations described below, the processor does not report and/or recover from the error(s) as intended.

- When a transaction is deferred during the snoop phase and subsequently receives a Hard Failure response, the transaction should be removed from the bus queue so that the processor may proceed. Instead, the transaction is not properly removed from the bus queue, the bus queue is blocked, and the processor will hang.
- When a hardware prefetch results in an uncorrectable tag error in the L2 cache, MC0_STATUS.UNCOR and MC0_STATUS.PCC are set but no Machine Check Exception (MCE) is signaled. No data loss or corruption occurs because the data being prefetched has not been used. If the data location with the uncorrectable tag error is subsequently accessed, an MCE will occur. However, upon this MCE, or any other subsequent MCE, the information for that error will not be logged because MC0_STATUS.UNCOR has already been set and the MCA status registers will not contain information about the error which caused the MCE assertion but instead will contain information about the prefetch error event.
- When the reporting of errors is disabled for Machine Check Architecture (MCA) Bank 2 by setting all MC2_CTL register bits to 0, uncorrectable errors should be logged in the IA32_MC2_STATUS register but no machine-check exception should be generated. Uncorrectable loads on bank 2, which would normally be logged in the IA32_MC2_STATUS register, are not logged.
- When one half of a 64 byte instruction fetch from the L2 cache has an uncorrectable error and the other 32 byte half of the same fetch from the L2 cache has a correctable error, the processor will attempt to correct the correctable error but cannot proceed due to the uncorrectable error. When this occurs the processor will hang.

- When an L1 cache parity error occurs, the cache controller logic should write the physical address of the data memory location that produced that error into the IA32_MC1_ADDR REGISTER (MC1_ADDR). In some instances of a parity error on a load operation that hits the L1 cache, however, the cache controller logic may write the physical address from a subsequent load or store operation into the IA32_MC1_ADDR register.
- The local xAPIC has an Error Status Register, which records all errors it detects. Bit 6 of this register, the Receive Illegal Vector bit, is set when the local xAPIC detects an illegal vector in a message that it received. When an illegal vector error is received on the same internal clock that the error status register is being written due to a previous error, bit 6 does not get set and illegal vector errors are not flagged.
- When an error exists in the tag field of a cache line such that a request for ownership (RFO) issued by the processor hits multiple tag fields in the L2 cache (the correct tag and the tag with the error) and the accessed data also has a correctable error, the processor will correctly log the multiple tag match error but will hang when attempting to execute the machine check exception handler.
- If a memory access receives a machine check error on both 64 byte halves of a 128-byte L2 cache sector, the IA32_MC0_STATUS register records this event as multiple errors, i.e., the valid error bit and the overflow error bit are both set indicating that a machine check error occurred while the results of a previous error were in the error-reporting bank. The IA32_MC1_STATUS register should also record this event as multiple errors but instead records this event as only one correctable error.
- The overflow bit should be set to indicate when more than one error has occurred. The overflow bit being set indicates that more than one error has occurred. Because of this erratum, if any further errors occur, the MCA overflow bit will not be updated, thereby incorrectly indicating only one error has been received.
- If an I/O instruction (IN, INS, REP INS, OUT, OUTS, or REP OUTS) is being executed, and if the data for this instruction becomes corrupted, the processor will signal a Machine Check Exception (MCE). If the instruction is directed at a device that is powered down, the processor may also receive an assertion of SMI#. Since MCEs have higher priority, the processor will call the MCE handler, and the SMI# assertion will remain pending. However, while attempting to execute the first instruction of the MCE handler, the SMI# will be recognized and the processor will attempt to execute the SMM handler. If the SMM handler is successfully completed, it will attempt to restart the I/O instruction, but will not have the correct machine state due to the call to the MCE handler. This can lead to failure of the restart and shutdown of the processor.
- If PWRGOOD is de-asserted during a RESET# assertion causing internal glitches, the MCA registers may latch invalid information.
- If RESET# is asserted, then de-asserted, and reasserted, before the processor has cleared the MCA registers, then the information in the MCA registers may not be reliable, regardless of the state or state transitions of PWRGOOD.
- If MCERR# is asserted by one processor and observed by another processor, the observing processor does not log the assertion of MCERR#. The Machine Check Exception (MCE) handler called upon assertion of MCERR# will not have any way to determine the cause of the MCE.
- The Overflow Error bit (bit 62) in the IA32_MC0_STATUS register indicates, when set, that a machine check error occurred while the results of a previous error were still in the error reporting bank (i.e. The Valid bit was set when the new error occurred). If an uncorrectable error is logged in the error-reporting bank and another error occurs, the overflow bit will not be set.

- The MCA Error Code field of the IA32_MC0_STATUS register gets written by a different mechanism than the rest of the register. For uncorrectable errors, the other fields in the IA32_MC0_STATUS register are only updated by the first error. Any further errors that are detected will update the MCA Error Code field without updating the rest of the register, thereby leaving the IA32_MC0_STATUS register with stale information.
- When a speculative load operation hits the L2 cache and receives a correctable error, the IA32_MC1_Status Register may be updated with incorrect information. The IA32_MC1_Status Register should not be updated for speculative loads.
- The processor should only log the address for L1 parity errors in the IA32_MC1_Status register if a valid address is available. If a valid address is not available, the Address Valid bit in the IA32_MC1_Status register should not be set. In instances where an L1 parity error occurs and the address is not available because the linear to physical address translation is not complete or an internal resource conflict has occurred, the Address Valid bit is incorrectly set.
- The processor may hang when an instruction code fetch receives a hard failure response from the system bus. This occurs because the bus control logic does not return data to the core, leaving the processor empty. IA32_MC0_STATUS MSR does indicate that a hard fail response occurred.
- The processor may hang when the following events occur and the machine check exception is enabled, CR4.MCE=1. A processor that has its STPCLK# pin asserted will internally enter the Stop Grant State and finally issue a Stop Grant Acknowledge special cycle to the bus. If an uncorrectable error is generated during the Stop Grant process it is possible for the Stop Grant special cycle to be issued to the bus before the processor vectors to the machine check handler. Once the chipset receives its last Stop Grant special cycle it is allowed to ignore any bus activity from the processors. As a result, processor accesses to the machine check handler may not be acknowledged, resulting in a processor hang.

Implication: The processor is unable to correctly report and/or recover from certain errors.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P11. Debug Mechanisms May Not Function as Expected

Problem: Certain debug mechanisms may not function as expected on the processor. The cases are as follows:

- When the following conditions occur: 1) An FLD instruction signals a stack overflow or underflow, 2) the FLD instruction splits a page-boundary or a 64 byte cache line boundary, 3) the instruction matches a Debug Register on the high page or cache line respectively, and 4) the FLD has a stack fault and a memory fault on a split access, the processor will only signal the stack fault and the debug exception will not be taken.
- When a data breakpoint is set on the ninth and/or tenth byte(s) of a floating-point store using the Extended Real data type, and an unmasked floating-point exception occurs on the store, the breakpoint will not be captured.

- When any instruction has multiple debug register matches, and any one of those debug registers is enabled in DR7, all of the matches should be reported in DR6 when the processor goes to the debug handler. This is not true during a REP instruction. As an example, during execution of a REP MOVSW instruction the first iteration a load matches DR0 and DR2 and sets DR6 as FFFF0FF5h. On a subsequent iteration of the instruction, a load matches only DR0. The DR6 register is expected to still contain FFFF0FF5h, but the processor will update DR6 to FFFF0FF1h.
- When the memory type is set to UC (Uncacheable) and a physical address code breakpoint is set, the processor will not break at the physical address code breakpoint and the machine will continue execution beyond the breakpoint.

Implication: Certain debug mechanisms do not function as expected on the processor.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P12. Processor May Live-lock if PDEs or PTEs are in UC Space

Problem: The processor may livelock under the following boundary conditions:

- The Page-Directory Entries (PDEs) or Page-Table Entries (PTEs) are in uncacheable (UC) space
- An instruction fetch misses the ITLB resulting in a page walk
- This instruction fetch is immediately followed by a store that splits a page boundary

Implication: When this erratum occurs, the processor will livelock. This erratum was found using random instruction testing and has not been observed with commercial software.

Workaround: It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P13. Thermal Status Log Bit May Not be Set when the Thermal Control Circuit is Active

Problem: Bit 1 of the IA32_THERM_STATUS register (Thermal Status Log) is a sticky bit designed to be set to '1' if the thermal control circuit (TCC) has been active since either the previous processor reset or software cleared this bit. If TCC is active and the Thermal Status Log bit is cleared by a processor reset or by software, it will remain clear (set to '0') as long as the TCC remains active. Once TCC deactivates, the next activation of the TCC will set the Thermal Status Log bit.

Implication: When this erratum occurs, the Thermal Status Log bit will be cleared (set to '0') although the thermal control circuit is active.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.



P14. Processor May Timeout Waiting For A Device To Respond After 0.67 Seconds

Problem: The PCI 2.1 target initial latency specification allows two seconds for a device to respond during initialization-time. The processor may timeout after only approximately 0.67 seconds. When the processor times out it will hang with IERR# asserted. PCI devices that take longer than 0.67 seconds to initialize may not be initialized properly.

Implication: System may hang with IERR# asserted.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P15. Cascading Of Performance Counters Does Not Work Correctly When Forced Overflow is Enabled

Problem: The performance counters are organized into pairs. When the CASCADE bit of the Counter Configuration Control Register (CCCR) is set, a counter that overflows will continue to count in the other counter of the pair. The FORCE_OVF bit forces the counters to overflow on every non-zero increment. When the FORCE_OVF bit is set, the counter overflow bit will be set but the counter no longer cascades.

Implication: The performance counters do not cascade when the FORCE_OVF bit is set.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P16. EMON Event Counting of x87 Loads May Not Work as Expected

Problem: If a performance counter is set to count x87 loads and floating-point exceptions are unmasked, the FPU Operand (Data) Pointer (FDP) may become corrupted.

Implication: When this erratum occurs, FPU Operand (Data) Pointer (FDP) may become corrupted.

Workaround: This erratum will not occur with floating point exceptions masked. If floating-point exceptions are unmasked, then performance counting of x87 loads should be disabled.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P17. Simultaneous Code Breakpoint and Uncorrectable Error Results in Processor Hang

Problem: If an instruction fetch results in an uncorrectable error and there is also a debug breakpoint at this address, the processor will hang and the uncorrectable error will not be logged in the Machine Check registers.

Implication: When this erratum occurs the processor will hang.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P18. Software Controlled Clock Modulation Using A 12.5% or 25% Duty Cycle May Cause The Processor To Hang

Problem: Per the ACPI 1.0b specification, processor clock modulation may be controlled via a processor register (IA32_THERM_CONTROL). The On-Demand Clock Modulation Duty Cycle is controlled by bits 3:1. If these bits are set to a duty cycle of 12.5% or 25%, the processor may hang while attempting to execute a floating-point instruction. In this failure, the last instruction pointer (LIP) is pointing to a floating-point instruction whose instruction bytes are in UC space and which takes an exception 16 (floating point error exception). The processor stalls trying to fetch the bytes of the faulting floating-point instruction and those following it. This processor hang is caused by interactions between the thermal control circuit and floating-point event handler.

Implication: When the clock modulation is set to 12.5% or 25% duty cycle, the processor will go into a sleep state from which it fails to return.

Workaround: Use a duty cycle other than 12.5% or 25%.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P19. RFO With ECC Error May Result In Incorrect Data

Problem: This erratum occurs as the result of the following conditions:

- A read for ownership (RFO) generates a correctable error.
- In the process of correcting the error, a locked RFO (LRFO) is issued that uses the same internal buffer as the previous RFO.
- Another processor issues a snoop to the same address as the LRFO.

An internal boundary condition exists which may prevent the LRFO from completing correctly causing the snoop to receive incorrect data. Intel has not been able to reproduce this erratum with commercial software.

Implication: When this erratum occurs, data corruption may result.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P20. Speculative Page Fault May Cause Livelock

Problem: If the processor detects a page fault, which is corrected before the operating system page fault handler can be called (e.g. a second processor or DMA activity modifies the page tables and the corrected page tables are left in a non-accessed or non-modified state) the processor may livelock. Intel has not been able to reproduce this erratum with commercial software.

Implication: This erratum occurs in systems where page tables are being modified by other processors. If this erratum is encountered, the processor will livelock resulting in a system hang or operating system failure.

Workaround: It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P21. PAT Index MSB May Be Calculated Incorrectly

Problem: When Mode B or Mode C paging support is enabled and all of the following events occur:

- A page walk returns the Page Directory Entry (PDE) for a large page from memory.
- A subsequent page walk returns the Page Table Entry (PTE) for a 4k page from memory and the Page Attribute Table (PAT) upper index bit in this PTE is set to 1b.

It is possible that the PAT upper index bit in the PTE is incorrectly ignored and assumed to be 0b. The result is that the memory type in the PAT that should have come from the corresponding PAT index [4-7] incorrectly comes from PAT index [0-3].

Implication: If an operating system has programmed the PAT in an asymmetrical fashion i.e. PAT[0-3] is different from PAT[4-7] then an incorrect memory type may be used.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P22. System Bus Interrupt Messages Without Data And Which Receive A HardFailure Response May Hang The Processor

Problem: When a system bus agent (processor or chipset) issues an interrupt transaction without data onto the system bus, and the transaction receives a HardFailure response, a potential processor hang can occur. The processor, which generates an inter-processor interrupt (IPI) that receives HardFailure response, will still log the MCA error event cause as HardFailure, even if the APIC causes a hang. Other processors, which are true targets of the IPI, will also hang on hardfailure-without-data, but will not record an MCA HardFailure event as a cause. If a HardFailure response occurs on a system bus interrupt message with data, the APIC will complete the operation so as not to hang the processor.

Implication: The processor may hang.

Workaround: None identified

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P23. SQRTPD and SQRTSD May Return QNaN Indefinite Instead of Negative Zero

Problem: When DAZ mode is enabled, and a SQRTPD or SQRTSD instruction has a negative denormal operand, the instruction will return a QNaN indefinite when the specified response should be zero.

Implication: When this erratum occurs, the instruction will return a QNaN indefinite when a zero is expected.

Workaround: Ensure that negative denormals are not used as operands to the SQRTPD or SQRTSD instructions when DAZ mode is enabled. Software could enable FTZ mode to ensure that negative denormals are not generated by computation prior to execution of the SQRTPD or SQRTSD instructions.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P24. Bus Invalidate Line Requests that Returns Unexpected Data May Result in L1 Cache Corruption

Problem: When a Bus Invalidate Line (BIL) request receives unexpected data from a deferred reply, and a store operation write combines to the same address, there is a small window where the L1 cache is corrupt, and loads can retire with this corrupted data. This erratum occurs in the following scenario:

- A Read-For-Ownership (RFO) transaction is issued by the processor and hits a line in shared state in the L2 cache.
- The RFO is then issued on the system bus as a 0 length Read-Invalidate (BIL), since it doesn't need data, just ownership of the cache line.
- This transaction is deferred by the chipset.
- At some later point, the chipset sends a deferred reply for this transaction with an implicit write-back response. For this erratum to occur, no snoop of this cache line can be issued between the BIL and the deferred reply.
- The processor issues a write-combining store to the same cache line while data is returning to the processor. This store straddles an 8-byte boundary.

Due to an internal boundary condition, a time window exists where the L1 cache contains corrupt data, which could be accessed by a load.

Implication: The L1 cache may contain corrupted data. No known commercially available chipsets trigger the failure conditions.

Workaround: The chipset could issue a BIL (snoop) to the deferred processor to eliminate the failure conditions.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.



P25. Multi-processor Boot Protocol may not Complete with an IOQ Depth of One

Problem: When the In-Order Queue (IOQ) depth is managed by the chipset to be one entry deep, the system may hang during the multi-processor boot protocol. This hang occurs when the chipset drives BNR# in such a way that the processors are continually throttled off the bus then released to access the bus in alternating cycles which never allows the multi-processor boot protocol to complete execution.

Implication: The system may hang during the multi-processor boot protocol.

Workaround: If the chipset drives BNR# in such a way that the processors are continually throttled off the bus then released to access the bus in alternating cycles, do not use In-Order Queue de-pipelining.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P26. Processor Flags #PF Instead of #AC on an Unlocked CMPXC8B Instruction

Problem: If a data page fault (#PF) and alignment check fault (#AC) both occur for an unlocked CMPXC8B instruction, then #PF will be flagged.

Implication: Software that depends #AC before #PF will be affected since #PF is flagged in this case.

Workaround: Remove the software's dependency on the fact that #AC has precedence over #PF. Alternately, if the reload is due to a not present page, reload the page in the page fault handler and then restart the faulting instruction.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P27. Incorrect Data may be Returned When Page Tables are Located in Write Combining (WC) Memory

Problem: If page directories and/or page tables are located in Write Combining (WC) memory, speculative loads to cacheable memory may complete with incorrect data.

Implication: Cacheable loads to memory mapped using page tables located in write combining memory may return incorrect data. Intel has not been able to reproduce this erratum with commercially available software.

Workaround: Do not place page directories and/or page tables in WC memory.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.

P28. FSW May not be Completely Restored after Page Fault on FRSTOR or FLDENV Instructions

Problem: If the FPU operating environment or FPU state (operating environment and register stack) being loaded by an FLDENV or FRSTOR instruction wraps around a 64-Kbyte or 4-Gbyte boundary and a page fault (#PF) or segment limit fault (#GP or #SS) occurs on the instruction near the wrap boundary, the upper byte of the FPU status word (FSW) might not be restored. If the fault handler does not restart program execution at the faulting instruction, stale data may exist in the FSW.

Implication: When this erratum occurs, stale data will exist in the FSW.

Workaround: Ensure that the FPU operating environment and FPU state do not cross 64-Kbyte or 4-Gbyte boundaries. Alternately, ensure that the page fault handler restarts program execution at the faulting instruction after correcting the paging problem.

Status: For the steppings affected see the *Summary of Changes* at the beginning of this section.



DOCUMENTATION CHANGES

The Documentation Changes listed in this section apply to the following documents:

- *Intel® Xeon™ Processor at 1.40 GHz, 1.50 GHz, and 1.70 GHz* datasheet (Order Number 249665)
- *IA-32 Intel® Architecture Software Developer's Manual, Volumes 1, 2 and 3* (Order Numbers 245470, 245471, and 245472, respectively)

All Documentation Changes will be incorporated into a future version of the appropriate Intel Xeon processor documentation.

There are no documentation changes to report.

SPECIFICATION CLARIFICATIONS

The Specification Clarifications listed in this section apply to the following documents:

- *Intel® Xeon™ Processor at 1.40 GHz, 1.50 GHz, and 1.70 GHz* datasheet (Order Number 249665)
- *IA-32 Intel® Architecture Software Developer's Manual, Volumes 1, 2 and 3* (Order Numbers 245470, 245471, and 245472, respectively)

All Specification Clarifications will be incorporated into a future version of the appropriate Intel Xeon processor documentation.

P1. RCPPS, RCPSS, RSQRTPS and RSQRTSS Instruction Specification Clarification

Volume 2: Instruction Set Reference Manual of the *IA-32 Intel Architecture Software Developer's Manual* (pages 3-665, 3-667, 3-685, 3-687) details the behavior of the RCPPS, RCPSS, RSQRTPS, and RSQRTPS instructions. The documentation for each instruction will be clarified to include the text below about the relative error for the instruction and the values for which flushing results to zero is performed:

The relative error for this approximation is: $|\text{Relative Error}| \leq 1.5 * 2^{-12}$

For the RCPPS and RCPSS instructions, tiny results are always flushed to 0.0, with the sign of the operand. (Input values greater than or equal to $|1.1111111110100000000000B * 2^{125}|$ are guaranteed to not produce tiny results, input values less than or equal to $|1.00000000000110000000001B * 2^{126}|$ are guaranteed to produce tiny results, which are in turn flushed to 0.0; and input values in between this range may or may not produce tiny results, depending on the implementation.) Underflow results are always flushed to 0.0, with the sign of the operand.



SPECIFICATION CHANGES

The Specification Changes listed in this section apply to the following documents:

- *Intel® Xeon™ Processor at 1.40 GHz, 1.50 GHz, and 1.70 GHz* datasheet (Order Number 249665)
- *IA-32 Intel® Architecture Software Developer's Manual, Volumes 1, 2 and 3* (Order Numbers 245470, 245471, and 245472, respectively)

All Specification Changes will be incorporated into a future version of the appropriate Intel Xeon processor documentation.

There are no specification changes to report.